



RENOVATE CLUBHOUSE - 1ST FLOOR

- NEW ENTRY FACING THOMPSON STREET
- NEW OPEN STAIR TO STRENGTHEN THE CONNECTION TO UPPER FLOOR LOUNGE AND MEETING ROOM
- RENOVATED MAIN FLOOR LOBBY & LOUNGE: NATURAL LIGHT & VIEWS, BETTER CONNECTION TO TENNIS COURTS
- RENOVATED KITCHEN: NATURAL LIGHT & VIEWS, BETTER CONNECTION TO BALLROOM
- MORE OPEN AND ACCESSIBLE FRONT DESK / SNACK BAR AREA
- RENOVATED CORRIDOR TO WEIGHT ROOM: OPEN VIEWS TO TENNIS COURTS, SKYLIGHTS, ELECTRICAL EQUIPMENT HIDDEN FROM VIEW
- NEW ROOF, EXTERIOR SIDING, WINDOWS: DESIGN TO BE MORE SYMPATHETIC TO THE HISTORIC NEIGHBORHOOD & CLUB BUILDINGS

The Irvington Club

Portland, Oregon

September 29, 2011

A1.0

PROPOSED FIRST FLOOR PLAN



S | E | A

Scott | Edwards Architecture LLP

2525 E Burnside Street
Portland, Oregon 97214
503.226.3617 phone
503.226.3715 fax
architects@sealp.com